

CONTENTS

	<u>Page</u>
Figures	iii
Tables	xi
1.0 Introduction	1-1
2.0 Reasonably Available Control Measures (RACM)	2-1
2.1 General Fugitive Dust Sources	2-3
2.1.1 Plant Roadways and Parking Areas	2-6
2.1.2 Aggregate Storage Piles	2-26
2.1.3 Material Handling	2-53
2.1.4 Mineral Extraction	2-65
2.2 Iron and Steel Mills	2-93
2.2.1 Coke Manufacturing	2-93
2.2.2 Iron Production	2-113
2.2.3 Steel Manufacture	2-134
2.3 Lime Plants	2-154
2.4 Power Plants	2-172
2.5 Grain Terminals	2-184
2.6 Country Grain Elevators	2-203
2.7 Iron Foundries	2-214
2.8 Steel Foundries	2-232
2.9 Glass Manufacturing Plants	2-242
2.10 Fiberglass Manufacturing	2-257
2.11 Secondary Aluminum Processing Plants	2-266
2.12 Fertilizer Mixing/Blending Plants	2-277
2.13 Cement Manufacturing and Blending Plants	2-289

CONTENTS (continued)

	<u>Page</u>
2.14 Ferroalloy Production	2-306
2.15 Metal Salvage Operations	2-320
2.16 Pulp and Paper Mills	2-329
2.17 Woodworking Operations	2-337
2.18 Aggregate Processing Plants	2-358
2.19 Coal Processing Plants	2-403
2.20 Brick and Related Clay Product Manufacturing Plants	2-445
2.21 Asphaltic Concrete Plants	2-459
2.22 Concrete Batching Plants	2-471
2.23 Sandblasting Operations	2-490
2.24 Petroleum Refineries	2-505
2.25 Agricultural Chemical Manufacturing Plants	2-513
2.26 Bulk Gasoline Terminals and Plants	2-524
2.27 Carbon Black Plants	2-532
2.28 Municipal Incineration	2-541
2.29 Salt Processing Operations	2-560
2.30 Galvanizing Plants	2-572
Appendix A: Cost Estimation Guidelines for RACM for Fugitive Dust	A-1
Appendix B: Listing of Chemical Dust Suppressants	B-1

FIGURES

<u>Number</u>		<u>Page</u>
2.1-1	Order and Location of General Fugitive Dust Sources in a Hypothetical Industrial Setting	2-4
2.1-2	Order and Location of General Fugitive Dust Sources in Hypothetical Mineral Mining Operation	2-5
2.1.2-1	Thornthwaite Precipitation-Evaporation (PE) Indices for the State of Ohio	2-28
2.1.2-2	Mean Number of Dry Days (Less Than 0.01 Inch of Precipitation) in the State of Ohio	2-36
2.1.3-1	Typical Materials Handling Operation	2-54
2.1.4-1	Overburden Removal Operations for Area and Contour Strip Mining	2-69
2.1.4-2	Climatic Factors for Use in the Wind Erosion Equation	2-81
2.2.1-1	Process Flow Diagram of Coke Manufacturing and Associated Fugitive Particulate Emission Sources	2-96
2.2.2-1	Blast Furnace Cross Section	2-113a
2.2.2-2	Blast Furnace Plant With Auxiliary Equipment	2-113b
2.2.2-3	Simplified Process Flow Diagram of Iron Production and Associated Fugitive Particulate Emission Sources	2-116
2.2.3-1	Cross-Section of an Open-Hearth Furnace	2-135a
2.2.3-2	Cross-Section of a Basic Oxygen Furnace	2-135b
2.2.3-3	Cross-Section of an Electric Arc Furnace	2-136a
2.2.3-4	Simplified Process Flow Diagram for Steel Manufacture and Associated Fugitive Particulate Emission Sources	2-139
2.2.3-5	BOF Total Furnace Enclosure System	2-143a
2.2.3-6	BOF Canopy Hood System	2-144a
2.2.3-7	Electric Furnace Building Evacuation System	2-145a

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.2.3-8	Electric Furnace Canopy Hood System	2-145b
2.3-1	Process Flow Diagram and Fugitive Emission Sources for Lime Manufacturing	2-155
2.3-2	Wet Dust Suppression System Applied on a Lime Plant	2-167
2.4-1	Simplified Process Flow Diagram of Coal-Fired Power Plants and Associated Fugitive Particulate Emission Sources	2-173
2.4-2	Wet Dust Suppression System Applied on a Coal-Fired Power Plant	2-181a
2.5-1	Simplified Process Flow Diagram for Grain Terminals and Associated Fugitive Particulate Emission Sources	2-185
2.5-2	Grain Terminal Elevator	2-185a
2.5-3	Truck Unloading	2-185b
2.5-4	Railcar Unloading	2-185c
2.5-5	Grain Cleaning Equipment	2-186a
2.5-6	Rack and Column Grain Dryers	2-186b
2.5-7	Railcar and Truck Loading	2-187a
2.5-8	Barge and Ship Loading	2-187b
2.5-9	Truck Unloading Control System	2-191a
2.5-10	Railcar Unloading Control System	2-192a
2.5-11	Boxcar Unloading Control System	2-192b
2.5-12	Barge Loading Control System	2-193a
2.5-13	Elevator Leg Control System	2-193b
2.5-14	Transfer Point Control System	2-193c
2.5-15	Grain Handling and Cleaning Control System	2-193d

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.5-16	Rack Dryer with Screen Filter	2-194a
2.5-17	Truck Loading Control System	2-194b
2.5-18	Boxcar Loading Control System	2-194c
2.5-19	Hopper Car Loading Control System	2-195a
2.5-20	Barge or Ship Loading Control System	2-195b
2.6-1	Simplified Process Flow Diagram for Country Grain Elevators and Associated Fugitive Particulate Emission Sources	2-204
2.6-2	Diagram of an Upright Country Grain Elevator	2-204a
2.7-1	Simplified Process Flow Diagram for Iron Foundries and Associated Fugitive Particulate Emission Sources	2-215
2.7-2	Iron Foundry Process Flow Diagram	2-215a
2.7-3	Cupola Furnace	2-215b
2.7-4	Electric Arc Furnace	2-216a
2.7-5	Channel Electric Induction Furnace	2-216b
2.7-6	Coreless Electric Induction Furnace	2-216c
2.7-7	Reverberatory Furnace	2-216d
2.7-8	Magnesium Treatment Methods for Producing Ductile Iron	2-216e
2.7-9	Sand Muller	2-217a
2.7-10	Building Evacuation System	2-223a
2.7-11	Mobile Tapping Hoods	2-223b
2.7-12	Hooded Pouring Station	2-224a
2.7-13	Movable Pouring Hood	2-224b
2.7-14	A Casting Shakeout Control System	2-224c
2.7-15	Capture Design for a Typical Sand-Handling System	2-224e

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.8-1	Simplified Process Flow Diagram for Steel Foundries and Associated Fugitive Particulate Emission Sources	2-233
2.9-1*	Simplified Process Flow Diagram for Manufacture of Soda-Lime Glass and Associated Fugitive Particulate Emission Sources	2-243
2.9-2	Side-Port Continuous Regenerative Furnace	2-245
2.9-3	End-Port Continuous Regenerative Furnace	2-246
2.10-1	Simplified Process Flow Diagram of Fiberglass Manufacture and Associated Fugitive Particulate Emission Sources	2-258
2.11-1	Simplified Process Flow Diagram for Secondary Aluminum Processing Plants and Associated Fugitive Particulate Emission Sources	2-267
2.12-1	Typical Flow Diagram for Fertilizer Mixing/Blending Facilities and Associate Fugitive Particulate Emission Sources	2-278
2.12-2	Bulk Loading Station With Elevated Storage Used in Fertilizer Mixing/Blending Plants	2-280
2.12-3	A Bulk Blending Plant With Fugitive Dust Emission Controls Consisting of Skirts Around Railcar Unloading and a Series of Hoods Ducted to a Fabric Filter	2-283a
2.12-4	Dust Suppressant Application System	2-283b
2.12-5	Bucket Elevators Used at Bulk Blending Plants	2-286a
2.13-1	Typical Rotary Ball Mill Configuration	2-292
2.13-2	Simplified Process Flow Diagram for Portland Cement Production and Associated Fugitive Particulate Emission Sources	2-293
2.14-1	Simplified Process Flow Diagram for Ferroalloy Production and Associated Fugitive Particulate Emission Sources	2-307
2.14-2	Submerged-Arc Furnace for Ferroalloy Production	2-309
2.15-1	Process Schematic for Metal Salvage/Auto Shredding Illustrating Potential Fugitive Particulate Emission Points	2-321

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.16-1	Simplified Process Flow Diagram for Raw Material Preparation for Wood Pulping Processes at Pulp and Paper Mills, and Associated Fugitive Particulate Emission Sources	2-330
2.16-2	Typical Kraft Sulfate Pulping and Recovery Process	2-332
2.17-1	Cross-Section of a Typical Wood Hogging Machine	2-341
2.17-2	Simplified Process Flow Diagram for Wood-working Operations at Several Wood Product Manufacturing Plants and Associated Fugitive Particulate Emission Sources	2-342
2.17-3	Cement-Receiving and Storage System	2-350
2.18-1	Simplified Process Flow Diagram for Sand and Gravel Processing Plants and Associated Fugitive Particulate Emission Sources	2-360
2.18-2	Simplified Process Flow Diagram for Crushed Stone Processing and Associated Fugitive Particulate Emission Sources	2-361
2.18-3	Simplified Process Flow Diagram for Slag Processing and Associated Fugitive Particulate Emission Sources	2-362
2.18-4	Double-Toggle Jaw Crusher	2-366
2.18-5	Single-Toggle Jaw Crusher	2-367
2.18-6	Pivoted-Spindle Gyratory Crusher	2-368
2.18-7	Cone Gyratory Crusher	2-368
2.18-8	Single-Roll Crusher	2-369
2.18-9	Double-Roll Crusher	2-370
2.18-10	Hammermill Crusher	2-370
2.18-11	Impact Crusher	2-371
2.18-12	Vibrating Grizzly	2-372
2.18-13	Vibrating Screen	2-372
2.18-14	Belt Conveyor Transfer Point	2-374
2.18-15	Types of Bucket Elevators	2-375

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.18-16	Wet Dust-Suppression System	2-385
2.18-17	Wet Dust-Suppression Application at a Crusher Discharge Point	2-387
2.18-18	Hood Configuration for a Transfer Point Having a Free-Fall Distance Less Than 3 Feet	2-388
2.18-19	Hooding Configuration for a Transfer Point Having a Free-Fall Distance Greater Than 3 Feet	2-389
2.18-20	A Combination Control System Consisting of Wet Suppression and Dry Collection	2-390
2.19-1	Simplified Process Flow Diagram for Coal Processing Plants and Associated Fugitive Particulate Emission Sources	2-405
2.19-2	A Coal Sizing Circuit at a Coal Preparation Plant	2-408
2.19-3	Rotary Breaker	2-409
2.19-4	Hammermill	2-410
2.19-5	Single-Roll Coal Crusher	2-411
2.19-6	Double-Roll Coal Crusher	2-411
2.19-7	Ring Coal Crusher	2-411
2.19-8	Pneumatic Cleaning Circuit	2-414
2.19-9	Air Table	2-415
2.19-10	Jig-Table Cleaning Circuit	2-416
2.19-11	Air-Pulsated Jig	2-417
2.19-12	Deister Table	2-417
2.19-13	Heavy-Media Cleaning Circuit	2-419
2.19-14	Heavy-Media Cyclone	2-420
2.19-15	Water Clarification Circuit	2-421
2.19-16	Froth Flotation Unit	2-423
2.19-17	Screen-Type Thermal Coal Dryer	2-425
2.18-18	Cascade Thermal Coal Dryer	2-425

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.19-19	Flash or Suspension Thermal Coal Dryer	2426
2.19-20	Multilouver Thermal Coal Dryer	2-427
2.19-21	Fluidized Bed Thermal Coal Dryer	2-428
2.20-1	Tunnel Kiln	2-448
2.20-2	Periodic Kiln	2-450
2.20-3	Simplified Process Flow Diagram for Brick and Related Clay Product Manufacturing Plants and Associated Fugitive Particulate Emission Sources	2-451
2.21-1	Simplified Process Flow Diagram for a Continuous Hot-Mix Asphaltic Concrete Plant and Associated Fugitive Particulate Emission Sources	2-460
2.21-2	Simplified Process Flow Diagram for a Batch Hot- Mix Asphaltic Concrete Plant and Associated Fugitive Particulate Emission Sources	2-461
2.21-3	Simplified Process Flow Diagram for a Dryer-Drum Asphaltic Concrete Manufacturing Plant and Associated Fugitive Particulate Emission Sources	2-463
2.22-1	Simplified Process Flow Diagram for Concrete Batching and Associated Fugitive Particulate Emission Sources	2-473
2.22-2	Cement-Receiving and Storage System	2-478
2.22-3	An Adjustable Gathering Hopper	2-481
2.23-1	Suction Blast Method	2-491
2.23-2	Direct Blast Method	2-492
2.23-3	Simplified Process Flow Diagram for Sandblasting and Associated Fugitive Particulate Emission Sources	2-494
2.23-4	Wet Blast Adaptor	2-499
2.24-1	Simplified Process Flow Diagram for Petroleum Refineries	2-506

FIGURES (continued)

<u>Number</u>		<u>Page</u>
2.25-1	Simplified Process Flow Diagram of the Urea Manufacturing Process and Associated Fugitive Particulate Emission Sources	2-515
2.26-1	Simplified Process Flow Diagram for Bulk Gasoline Distribution and Storage and Associated Fugitive Particulate Emission Sources	2-526
2.26-2	Simplified Process Flow Diagram for Bulk Gasoline Storage	2-527
2.26-3	Splash Loading Method	2-528
2.26-4	Submerged Fill Pipe	2-529
2.26-5	Bottom Fill Loading	2-530
2.27-1	Simplified Process Flow Diagram for Carbon Black Plants and Associated Fugitive Particulate Emission Sources	2-535
2.28-1	Simplified Process Flow Diagram of a Municipal Incinerator and Associated Fugitive Particulate Emission Sources	2-542
2.29-1	Simplified Process Flow Diagram for Salt Processing Operations and Associated Fugitive Particulate Emission Sources	2-563
2.30-1	Simplified Process Flow Diagram for Galvanizing Plants and Associated Fugitive Particulate Emission Sources	2-573

TABLES

<u>Number</u>		<u>Page</u>
2.1.1-1	Emission Factors for Vehicles Travelling Paved Surfaces	2-9
2.1.1-2	Typical Size Distribution of Fugitive Dust Particles by Surface Type	2-11
2.1.1-3	Summary of Techniques, Efficiencies and Costs for Controlling Fugitive Dust from Paved and Unpaved Surfaces	2-16
2.1.1-4	Contract Cost Estimates for Oiling Unpaved Roadways	2-19
2.1.2-1	Percent Contribution of Aggregate Storage Pile Activities Toward the Total Fugitive Emission Rate	2-29
2.1.2-2	Representative Silt Content, Moisture Content and the Duration of Storage Parameters for Specific Storage Materials	2-32
2.1.2-3	Thirty-Year Annual Wind Speed for Selected Ohio Cities	2-34
2.1.2-4	Vehicular Activity Factors	2-37
2.1.2-5	Summary of Emission Factor Equations and Correction Parameters	2-39
2.1.2-6	Typical Particulate Size Ranges for Fugitive Dust from Aggregate Storage Piles	2-40
2.1.2-7	Chemical Stabilizing Agents for Use on Aggregate Storage Piles	2-45
2.1.2-8	A Summary of Control Techniques, Efficiencies and Costs for Fugitive Dust Emissions from Aggregate Storage Piles	2-47

TABLES (continued)

<u>Number</u>		<u>Page</u>
2.1.3-1	Emission Factors for the Unloading of Material	2-56
2.1.3-2	Emission Factors for the Conveying and Transfer of Material	2-57
2.1.3-3	A Summary of Control Techniques, Efficiencies and Costs for Fugitive Emissions from Unloading, Conveying, and Transfer Operations	2-62
2.1.4-1	Mineral Mining in Ohio	2-66
2.1.4-2	Review of Fugitive Dust from Mineral Extraction Industry	2-67
2.1.4-3	Fugitive Dust Emission Factors for Overburden Removal Operations	2-72
2.1.4-4	Fugitive Dust Emission Factors for Drilling and Blasting Operations	2-75
2.1.4-5	Fugitive Dust Emission Factors for Truck Loading Operations	2-76
2.1.4-6	Fugitive Dust Emissions for Heavy Earthwork Construction Around Waste Disposal Sites	2-78
2.1.4-7	Summary of Variables for the Wind Erosion Equation	2-80
2.1.4-8	Particulate Size Distribution for Selected Mine Emission Sources	2-83
2.1.4-9	A Summary of Control Techniques, Efficiencies and Cost for Fugitive Emissions from Mineral Extraction Activities	2-90
2.2.1-1	Fugitive Dust Emission Factors for Coke Manufacturing	2-97
2.2.1-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources in Coke Manufacturing	2-104,105,106
2.2.2-1	Fugitive Dust Emission Factors for Iron Production	2-117,118

TABLES (continued)

<u>Number</u>		<u>Page</u>
2.2.2-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources in Iron Production	2-125,126, 2-127,128
2.2.3-1	Fugitive Dust Emission Factors for Steel Manufacturing	2-141
2.2.3-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources in Steel Manufacturing	2-147,148
2.3-1	Fugitive Dust Emission Factors for Lime Manufacturing	2-158
2.3-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Lime Plants	2-163,164,165
2.4-1	Fugitive Dust Emission Factors for Coal-Fired Power Plants	2-175
2.4-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Coal-Fired Power Plants (500 MW)	2-178,179,180
2.5-1	Fugitive Dust Emission Factors for Grain Terminals	2-188
2.5-2	Particulate Size Distribution for Dust from an Elevator Leg Cyclone (Inlet Test)	2-190
2.5-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Grain Terminals	2-196,197
2.6-1	Fugitive Dust Emission Factors for Country Grain Elevators	2-207
2.6-2	Particulate Size Distribution for Dust from an Elevator Leg Cyclone (Inlet Test)	2-209
2.6-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Country Grain Elevators	2-210,210a
2.7-1	Fugitive Dust Emission Factors for Iron Foundries	2-219

TABLES (continued)

<u>Number</u>		<u>Page</u>
2.7-2	Particulate Emission Characteristics for Various Foundry Operations	2-221, 221a
2.7-3	Chemical Composition of Cupola Dust	2-221b
2.7-4	Particle Size Distribution of Dust Emissions from Both Cold and Hot Blast Cupola Furnace Stacks	2-221b
2.7-5	Size Distribution for Particulate Emissions from Eighteen Cupola Furnace Installations	2-221b
2.7-6	Chemical Analysis of Particulate Emissions from an Electric Arc Furnace	2-221c
2.7-7	Particle-Size Distribution for Particulate Emissions from Three Electric-Arc Furnace-Installations	2-221d
2.7-8	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Iron Foundries	2-226, 227, 228
2.8-1	Fugitive Dust Emission Factors for Steel Foundries	2-235
2.8-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Steel Foundries	2-237, 238
2.9-1	Fugitive Dust Emission Factors for Glass Manufacturing Plants	2-249
2.9-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Glass Manufacturing Plants	2-251
2.10-1	Fugitive Dust Emission Factors for Fiberglass Manufacturing	2-260
2.10-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Fiberglass Manufacturing Plants	2-262
2.11-1	Fugitive Dust Emission Factors for Secondary Aluminum Processing Plants	2-271
2.11-2	Effluent Characteristics from Secondary Aluminum Production	2-270

TABLES (continued)

<u>Number</u>		<u>Page</u>
2.11-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Secondary Aluminum Processing Plants	2-274,274a
2.12-1	Fugitive Dust Emission Factors for Fertilizer Mixing/Blending Plants	2-282
2.12-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Fertilizer Mixing and Blending Plants	2-284,285
2.13-1	Raw Materials Used in Producing Portland Cement in the United States	2-290
2.13-2	Fugitive Dust Emission Factors for Cement Production	2-295
2.13-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Cement Manufacturing and Blending Plants	2-301,302,303
2.14-1	Fugitive Dust Emission Factors for Ferroalloy Production	2-311
2.14-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Ferroalloy Production Plants	2-314,315
2.15-1	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Metal Salvage Operations	2-323,324
2.17-1	Fugitive Dust Emission Factors for Woodworking Operations	2-344
2.17-2	Approximate Size Range of Typical Components of Wood Fuel	2-346
2.17-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources in Woodworking Operations	2-352,353,354
2.18-1	Fugitive Dust Emission Factors for Aggregate Processing Plants	2-378,379
2.18-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Aggregate Processing Plants	2-395,396,397

TABLES (continued)

<u>Number</u>		<u>Page</u>
2.19-1	Coal Size Ranges for Cleaning Equipment	2-412
2.19-2	Fugitive Dust Emission Factors for Coal Processing Plants	2-431
2.19-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Coal Processing Plants	2-437, 438, 439, 440
2.20-1	Fugitive Dust Emission Factors for Brick and Related Clay Product Manufacturing Plants	2-453
2.20-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Brick and Related Clay Product Manufacturing Plants	2-456
2.21-1	Fugitive Dust Emission Factors for Asphaltic Concrete Manufacturing	2-465
2.22-1	Fugitive Dust Emission Factors for Concrete Batching Plants	2-474
2.22-2	Physical Characteristics of Three Common Grades of Cement	2-475
2.22-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Concrete Batching Plants	2-484, 485, 486
2.23-1	Fugitive Dust Emission Factors for Sandblasting Operations	2-495
2.23-2	Typical Size Distribution of Fugitive Dust Particles as a Result of Sandblasting	2-496
2.23-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sandblasting Operations	2-501
2.25-1	Fugitive Dust Emission Factors for Urea Manufacturing	2-518
2.25-2	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Agricultural Chemical Manufacturing Plants	2-521

TABLES (continued)

<u>Number</u>		<u>Page</u>
2.27-1	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Carbon Black Plants	2-538
2.28-1	Fugitive Dust Emission Factors for Municipal Incineration	2-545
2.28-2	Range in Composition of Residential Solid Wastes in 21 U.S. Cities	2-547
2.28-3	Typical Composition of Municipal Solid Waste	2-548
2.28-4	Examples of Hazardous Wastes in Municipal Solid Waste	2-550
2.28-5	Physical Properties of Particles Leaving Furnace	2-551
2.28-6	Chemical Analysis of Flyash Samples from South Shore Incinerator, New York City, by Source	2-552
2.28-7	Spectrographic Analysis of Ashed Incinerator Particulate Matter	2-553
2.28-8	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Municipal Incineration	2-556
2.29-1	Specification Guidelines for Different Grades of Salt	2-561
2.29-2	A Summary of the Control Alternatives, Efficiencies and Costs; and the RACM Selections for Fugitive Dust Emissions from Salt Processing Operations	2-568, 569
2.30-1	Fugitive Dust Emission Factors for Galvanizing Plants	2-577
2.30-2	Chemical Analyses of the Fumes Collected by a Baghouse and by an Electrostatic Precipitator from Zinc Galvanizing Kettles	2-579
2.30-3	A Summary of the Control Alternatives, Efficiencies and Costs, and the RACM Selections for Fugitive Dust Emissions from Sources at Galvanizing Plants	2-583