

*** DRAFT – NOT FOR FILING ***

3745-520-642

Phase completion.

- (A) Not later than thirty days after completing disposal in a phase, an owner or operator shall survey the top of the disposed waste and create a topographic map and isopach of the C&DD facility that conform to rule 3745-520-605 of the Administrative Code. The drawings shall be made available to the approved board of health and Ohio EPA upon request.
- (B) Not later than thirty-one days after beginning disposal in a new phase, an owner or operator shall begin constructing either cap system or transitional cover over those areas of the previous phase in accordance with the phasing plan.