

3745-68-81 Closure.

At closure, the owner or operator must remove all hazardous waste and hazardous waste residues (including, but not limited to, ash) from the thermal treatment process or equipment.

[Comment: At closure, as throughout the operating period, unless the owner or operator can demonstrate, in accordance with paragraph (C) or (D) of rule 3745-51-03 of the Administrative Code, that any waste removed from the thermal treatment process or equipment is not a hazardous waste, the owner or operator becomes a generator of hazardous waste and must manage such waste in accordance with all applicable requirements of Chapters 3745-52, 3745-53, 3745-65 to 3745-69, and 3745-256 of the Administrative Code.]

Effective: 12/07/2004

119.032 review dates: Exempt

Promulgated under: 119.03

Statutory authority: 3734.12

Rule amplifies: 3734.12

Prior effective dates: 04/15/1981, 01/07/1983