

Ohio EPA Policy	Water Quality Modeling Field Manual	
DSW-0700.010 Removed	Statutory references: Rule references:	Ohio EPA, Division of Surface Water Revision 0, June 1, 1993 Revision 1, September 30, 1999 Removed, December 21, 2006
THIS POLICY DOES NOT HAVE THE FORCE OF LAW Pursuant to Section 3745.30 of the Revised Code, this policy was reviewed and removed.		

This policy does not meet the definition of policy contained in Section 3745.30 of the Ohio Revised Code. Ohio EPA is removing this document from the Division of Surface Water Policy Manual.

For more information contact:

Ohio EPA, Division of Surface Water
Modeling & Assessment Section
P.O. Box 1049
Columbus OH 43216-1049
(614) 644-2001

Ohio EPA Policy	Water Quality Modeling Field Manual	
DSW-0700.010	Statutory reference: ORC 6111.03 Rule reference: OAC 3745-2	Ohio EPA, Division of Surface Water Revision 0, June 1, 1993
Final	Revision 1, September 30, 1999	
THIS POLICY DOES NOT HAVE THE FORCE OF LAW Pursuant to Section 3745.30 of the Revised Code, this policy was reviewed on the last revision date.		

Purpose

The Water Quality Modeling Field Manual provides detailed instructions to Ohio EPA staff and other professionals charged with collecting chemical and physical measurements used in water quality modeling applications.

Background

The field manual is intended to provide a reference to the most frequently used Modeling Unit field methods, equipment operating instructions and quality assurance practices. The manual is believed compatible with state and federal regulations and the Division of Environmental Services Manual of Laboratory Standard Operating Procedures. The regulations and/or the Manual of Laboratory Standard Operating Procedures will take precedence if there are any contradictions.

Procedure

The report is only available in hard copy. Contact the office listed below for more information.

Related Policy or guidance

Ohio EPA. 1995. Manual of Ohio EPA Laboratory Standard Operating Procedures. Volumes I, II, III and IV.

For more information contact:

Ohio EPA, Division of Surface Water
Monitoring and Assessment Section
P.O. Box 1049
Columbus OH 43216-1049
(614) 644-2001

P:\SHARE\Sts\Policy\RE_POLMA\07_10U.WPD