

\*\*\* DRAFT – NOT FOR FILING \*\*\*

3745-506-130

Operation and maintenance of ground water monitoring wells, piezometers, and other measurement, sampling, and analytical devices.

(A) Throughout the duration of the ground water monitoring program, an owner or operator shall operate and maintain the ground water monitoring wells, piezometers, and other measurement, sampling, and analytical devices to perform to design specifications.

(B) The owner or operator shall identify and record each ground water monitoring well maintenance problem.

(C) The owner or operator shall develop a blank ground water monitoring well maintenance form that shall be used to record an identified well maintenance problem. At a minimum, this form shall include places to record the following:

(1) Name of the facility.

(2) Facility identification number assigned by Ohio EPA, if applicable.

(3) Ground water monitoring well identification number.

(4) Description of well maintenance problem.

(5) Date the well maintenance problem was identified.

(6) Date the well maintenance problem was corrected.

(7) Action taken to correct the well maintenance problem.

(D) If a ground water well maintenance problem is identified, the owner or operator shall correct the problem immediately. The completed well maintenance form shall be submitted to Ohio EPA and the approved board of health not later than seventy-five days after the well maintenance problem is identified.