

## North Cove Landfill - Toledo



Installation of concrete-filled fabric blanket on the bank of the Ottawa River to prevent erosion of the river bank.



Covering the concrete-filled fabric blanket with topsoil to promote natural vegetation,



Compacting and covering the east edge of the North Cove Landfill. I-75 is in the background.



Portion of Former North Cove Landfill before remediation.



Portion of former North Cove Landfill after remediation and establishment of a city park with walking trails.